


~~SECRET~~

Sanitized Copy Approved for Release 2010/04/21 : CIA-RDP61-00763A000100110160-5



~~SECRET~~ DPD-3051  
Cy 5 of 5

4 May 1959

MEMORANDUM FOR: Chief, Materiel Branch, DPD

ATTENTION

SUBJECT : Granger Associates

25X1

1. In a telephone conversation this date between Granger Associates and [ ] of this office, the following items requiring your action were discussed.

25X1

2. a. The ten improved video amplifiers and six new blowers for [ ] are being shipped to the [ ] today. We understand that the warehouse in turn has been instructed to air ship this equipment to [ ] as soon as possible. This equipment has taken new production items which in turn will be fitted with the reworked items to be returned by [ ] Therefore, steps should be taken to have [ ] return old parts by air as soon as possible and the Agency facility receiving them in the ZI should be instructed to transship to Granger immediately.

25X1

25X1

25X1

25X1

b. Granger has completed work on two Model 303 receivers under contract number 109-12454-9, and is prepared to deliver same to GSA, San Francisco this week. These two receivers belong to the "test bed" RB-69A aircraft now at Lockheed, and San Francisco should be instructed to pick them up and transship to Lockheed Aircraft Corporation, Burbank, California, for [ ] Plant C-1.

25X1

c. Granger has yet to receive the field service and maintenance contract; however, they have performed advance work on it, having been officially notified by contracts that it was approved. Per past conversations, the contract should be in the amount of \$15,000 ending on 30 June and should be renewed in the amount of \$30,000 for Fiscal 1960.

d. [ ] still has one of the original 502 receivers sent out on their first aircraft and retained when other original equipment was returned. The reason it was retained was due to the unavailability of a Traveling Wave Tube for the replacement equipment sent to [ ] on the second aircraft. At this time, Granger has the necessary tube (GA-36) which should be picked up and air shipped to [ ]. The original 302 receiver should be returned to Granger for retrofit.

25X1

25X1

25X1

SIGNED

[ ]  
Colonel, USAF  
Chief, Operations Branch  
DPD-DD/P

25X1

DPD-DD/P:WTH/aem

Dist.: Orig. & cy - addressee  
Cy #3 - OPS/DPD subj file  
Cy #1 - OPS/DPD Chief P17a

~~SECRET~~

25 YEAR  
RE-REVIEW

Sanitized Copy Approved for Release 2010/04/21 : CIA-RDP61-00763A000100110160-5